



OFFICE OF THE MARION COUNTY SURVEYOR  
SECTION RECORD CORNER  
SECTION 34 TOWNSHIP 17 RANGE 5  
DATE: -5-21-99- 8-4-04  
PARTY CHIEF: Wilcoxon  
CREW: \_\_\_\_\_  
TYPE OF MARKER: Boat spike found at surface  
METHOD OF ESTABLISHMENT: County: 10-12-94  
  
IN. S.P.C. E ZONE, NAD 83  
NAME: 17053406  
N: 513898.5720(m)  
E: 76782.6020(m)



Section Corner History: Original post set 1821 by Laughlin with witnesses: 14" beech N 23 W 22 links, 16" beech S 23 E 16 links. Legal Survey 2-1849 by Hosbrook per Lawrence Township Legal Survey Book pg. 16 & 41 called corner "G" with one witness still standing. 11-10-48 Thompson called stone set 6" down. 8-22-63 Burres reflected '48 ties, but not the type of monument. 5-30-72 SeFranka reflect previous ties and called corner bent and iron pin 0.3' down. 5-5-75 Fortner called PK nail over iron pin. 5-22-71 Hancock County called brass plug & plate set over stone. 5-23-77 MCS reflects same ties. Re-tied 8-17-92 by Green. Re-tied 10-12-94 by Wilcoxon. Re-tied 5-21-99 by Wilcoxon.

SC753406

REF.	DISTANCE	DESCRIPTION
1.	<del>23.44'</del>	Found PK nail S gas & utility post 6' up
2.	58.50'	PK nail N PwP no# 20' up
3.	<del>29.05'</del>	PK nail E PwP no# 10' up
4.	51.74'	Found PK nail W gas & utility post 12' up
5.	25.68'	Found PK nail E PwP#30-321HA 12' up (Mag nail w/brass washer )
6.	58.46'	PwP#47-321HA 14' up (Mag nail w/brass washer N)
7.	79.58'	Top nut of fire hydrant